


BE AWARE OF BELT WEAR

Today's belts require A DIFFERENT INSPECTION PROCESS.



BELT SLIP

damages the belt, creates noise, decreases accessory efficiency and could trigger a check engine light



THE NEW GATES BELT WEAR GAUGE

measures rubber loss, which can result in reduced power transfer from the crank to the accessories.



Start inspecting the **SERPENTINE, COOLING** and TIMING SYSTEMS at

060000 miles

REPLACE

worn components by

090000

miles

or as advised by the manufacturer

BELT NOISE

A recent survey by the Car Care Council found that 1 in every 6 Cars ON THE ROAD TODAY NEEDS A NEW BELT.



















is a symptom of a system issue and can be caused by loss of tension from:

A WORN BELT OR A FAILING TENSIONER

Belt noise is one of the leading causes of customer complaints.

Gates Century™ Series belts will give you unbeatable durability and performance.

> Lasts up to (50%)



longer than standard belts